

Contents

Executive Summary	ES-1
Section 1 Introduction	
1.1 Background	1-1
1.2 Review of Project Tasks	1-2
1.3 Summary of Work Completed.....	1-5
Section 2 USEPA Storm Water Compliance	
2.1 USEPA Phase II Storm Water Program.....	2-1
2.2 Designation under the Phase II Program.....	2-1
2.2.1 Automatic Designation.....	2-2
2.2.2 Potential Designation.....	2-2
2.2.3 Watershed Plan.....	2-3
2.3 Overview of Phase II.....	2-3
2.3.1 Requirements	2-4
2.3.2 Schedule.....	2-4
2.4 Storm Water Management Program.....	2-5
2.4.1 Six Minimum Controls	2-5
2.4.2 Selection of BMPs	2-6
2.4.3 Reference to Existing Programs.....	2-6
2.4.4 Measurable Goals	2-6
2.4.5 Applying for a Permit.....	2-7
Section 3 Geographic Information System Updates	
3.1 Introduction and Scope	3-1
3.2 Study Area	3-1
3.3 City-Wide Mapping	3-2
3.4 Custom Applications for Concord GIS.....	3-2
3.5 Recommendations and Next Steps.....	3-3
Section 4 Detailed Study Area No.1: "Terrible Trapezoid"	
4.1 Introduction.....	4-1
4.1.1 Study Area.....	4-1
4.1.2 Scope	4-1
4.1.3 Existing Storm Water System	4-3
4.2 Hydrology and Hydraulic Analysis	4-5
4.2.1 Selection of Design Storm	4-5
4.2.2 Study Area Delineation	4-6
4.2.3 Subcatchment Development.....	4-9
4.2.4 Model Selection.....	4-9

4.3	Runoff Development.....	4-11
4.3.1	Percent Impervious	4-11
4.3.2	Soil Parameters	4-11
4.3.3	Slope	4-11
4.3.4	Size of Subcatchments.....	4-11
4.4	EXTRAN Development	4-12
4.4.1	Pipe and System Characteristics	4-12
4.4.2	Roughness	4-12
4.4.3	Geometry of Main Drains.....	4-12
4.5	Evaluation of Current Conditions.....	4-15
4.5.1	Design Storms	4-15
4.5.2	Problem Areas.....	4-19
4.6	TV Inspection Program.....	4-20
4.6.1	Discussion.....	4-21
4.6.2	TV Inspection Summary of Recommendations	4-32
4.7	Recommendations	4-33
Section 5	Detailed Study Area No. 2: “Washington Street”	
5.1	Introduction	5-1
5.2	Study Area.....	5-1
5.3	Scope and Methods	5-1
5.3.1	Mapping.....	5-1
5.3.2	Toughbook Computer	5-2
5.3.3	Scope of Inspections in Basin.....	5-2
5.3.4	Scope of Inspection.....	5-3
5.3.5	Follow-up	5-4
5.4	Findings	5-4
5.5	Recommendations	5-7
Section 6	Remaining Sub-Basin Investigations	
6.1	Introduction.....	6.1-1
6.2	Rational Method, Spreadsheet Model	6.2-1
6.2.1	Modelization of Sub-Basin	6.2-1
6.2.2	Travel Time through Subcatchment (Tt).....	6.2-1
6.2.3	Time of concentration for Subcatchment (Tc)	6.2-2
6.2.4	Runoff Coefficient and Area	6.2-3
6.2.5	Connectivity	6.2-8
6.2.6	Final Calculations	6.2-8
6.2.7	Summary	6.2-10
6.3	Heights Drainage Basin Evaluation	6.3-1
6.3.1	Drainage Basin Description	6.3-1
6.3.2	Model Development	6.3-3
6.3.3	Recommendations	6.3-3

6.4	Turkey River Drainage Basin Evaluation.....	6.4-1
6.4.1	Drainage Basin Description	6.4-1
6.4.2	Model Development	6.4-2
6.4.3	Recommendations	6.4-2
6.5	Penacook Drainage Basin Evaluation.....	6.5-1
6.5.1	Drainage Basin Description	6.5-1
6.5.2	Model Development	6.5-3
6.5.3	Recommendations	6.5-3
6.6	Fisherville Drainage Basin Evaluation	6.6-1
6.6.1	Drainage Basin Description	6.6-1
6.6.2	Model Development	6.6-2
6.6.3	Recommendations	6.6-3
6.7	Oak Hill Sub-Basin	6.7-1
6.7.1	Drainage Basin Description	6.7-1
6.7.2	Model Development	6.7-3
6.7.3	Recommendations	6.7-4
6.8	Hospital Drainage Basin Evaluation, Amendment 3, Task 22.....	6.8-1
6.8.1	Drainage Basin Description	6.8-1
6.8.2	Model Development	6.8-2
6.8.3	Recommendations	6.8-2
6.9	Horseshoe Pond Drainage Basin Evaluation.....	6.9-1
6.9.1	Drainage Basin Description	6.9-1
6.9.2	Model Development	6.9-4
6.9.3	Recommendations	6.9-4
6.10	Turkey Pond Drainage Basin Evaluation.....	6.10-1
6.10.1	Drainage Basin Description	6.10-1
6.10.2	Model Development	6.10-2
6.10.3	Recommendations	6.10-3
6.11	West Concord Drainage Basin Evaluation.....	6.11-1
6.11.1	Drainage Basin Description	6.11-1
6.11.2	Model Development	6.11-3
6.11.3	Recommendations	6.11-4
6.12	Hoit Drainage Basin Evaluation.....	6.12-1
6.12.1	Drainage Basin Description	6.12-1
6.12.2	Model Development	6.12-2
6.12.3	Recommendations	6.12-4

Section 7 Outfall Inspections

7.1	Introduction	7-1
7.2	Background	7-1
7.3	Screening Procedure.....	7-2
7.4	Results of CDM Investigation.....	7-3

7.5	City Investigation	7-9
7.6	Conclusions and Recommendations.....	7-9
Section 8	Evaluating Funding Mechanisms for a Storm Sewer Enterprise	
8.1	Introduction.....	8-1
8.2	Funding alternatives	8-1
8.3	General Fund.....	8-2
8.4	Village Districts.....	8-3
8.5	Storm Water Funding Through Sewer Use Fees.....	8-5
8.6	Storm Sewer Enterprise Fund/Storm Water Utility.....	8-6
8.7	Summary.....	8-8
Section 9	Project Prioritization, BMPs and Rehabilitation Measures	
9.1	Prioritization Criteria	9-1
	9.1.1 Property/Traffic Impacts	9-2
	9.1.2 Pipe Size	9-2
	9.1.3 Percent Undersized	9-3
	9.1.4 Recurrence of the Problem	9-3
	9.1.5 Pipe Age.....	9-3
	9.1.6 Stream Impacts	9-4
	9.1.7 Constructability	9-4
	9.1.8 Potential Road Projects	9-5
	9.1.9 Prioritization Criteria Summary.....	9-5
9.2	Best Management Practices (BMPs).....	9-6
9.3	Rehabilitation Measures	9-8
9.4	Summary.....	9-9
Section 10	Capital Improvements Plan (CIP)	
10.1	Summary of Projects	10-1
10.2	Project Costs	10-2
10.3	Recommendations	10-2
10.4	Summary and Conclusions	10-3
Appendices		
	<i>Appendix A</i> Runoff and Extran Input files for Terrible Trapezoid	
	<i>Appendix B</i> Washington Street Inspection Reports	
	<i>Appendix C</i> “Manual” for Use in Report Creation from Electronic Database	
	<i>Appendix D</i> Photos of Select Manholes and Pipes from Washington Street Basin	
	<i>Appendix E</i> Detail Sketches from Washington Street Manhole Inspection	
	<i>Appendix F</i> Photos of Select Outfalls from Merrimack River Study	
	<i>Appendix G</i> Field Sheets for Outfall Inspections	

Tables

Section 1	Introduction	
1-1	Project Tasks and Descriptions	1-2
1-2	Work Completed by Project Task.....	1-5
1-3	Work Remaining by Project Task.....	1-5
Section 4	Detailed Study Area No.1: “Terrible Trapezoid”	
4-1	Rainfall Depths of Design Storms	4-6
4-2	EXTRAN Subcatchment Characteristics	4-10
4-3	Model-Identified Problem Locations and Related Design Storm Elevations	4-18
4-4	Scoring System for Pipe Defects	4-23
4-5	Drain Pipe Defects Found During TV Inspection	4-24
4-6	Drain Pipes Ranked in Order of Severity of Defects	4-29
4-7	Drain Pipes With Blockage and Miscellaneous Defects	4-31
4-8	Sections of Drain Pipe Identified as Possibly Having Active Services	4-34
4-9	Prioritized Recommendations Based Upon TV Inspection Score.....	4-35
Section 5	Detailed Study Area No. 2: “Washington Street”	
5-1	Priority Problems Identified During Manhole Inspection Program	5-6
Section 6	Remaining Sub-Basin Investigations	
6.2-1	Sample Model Output – “Tc-Calcs” Spreadsheet Time of concentration Calculations	6.2-5
6.2-2	Sample Model Output – “Project Area” Spreadsheet Connectivity and Flow Calculations.....	6.2-6
6.2-3	Runoff Coefficient by Landuse	6.2-3
6.3-1	Heights Known Problems and Issues	6.3-2
6.3-2	Heights Detention Ponds	6.3-3
6.3-3	Heights Drainage Basin Calculations	6.3-5
6.3-4	Known and/or Suspected Problems in Heights	6.3-4
6.4-1	Turkey River Drainage Basin Calculations.....	6.4-4
6.4-2	Known and/or Suspected Problems the Turkey River Basin.....	6.4-3
6.5-1	Penacook Known Problems and Issues.....	6.5-2
6.5-2	Penacook Detention Ponds	6.5-3
6.5-3	Penacook Drainage Basin Calculations	6.5-6
6.5-4	Known and/or Suspected Problems in the Penacook Basin.....	6.5-4
6.6-1	Fisherville Known Problems and Issues	6.6-2
6.6-2	Fisherville Detention Basins.....	6.6-3
6.6-3	Fisherville Drainage Basin Calculations.....	6.6-5
6.6-4	Known and/or Suspected Problems in the Fisherville Basin	6.6-4
6.7-1	Oak Hill Known Problems and Issues.....	6.7-3

6.7-2	Oak Hill Detention Ponds	6.7-4
6.7-3	Oak Hill Drainage Basin Model Results.....	6.7-6
6.7-4	Known and/or Suspected Problems in Oak Hill.....	6.7-5
6.8-1	Hospital Known Problems and Issues	6.8-2
6.8-2	Hospital Drainage Basin Calculations.....	6.8-5
6.8-3	Known and/or Suspected Problems in the Hospital Basin.....	6.8-3
6.9-1	Horseshoe Pond Known Problems ad Issues	6.9-4
6.9-2	Known and/or Suspected Problems in Horseshoe Pond Basin	6.9-5
6.9-3	Horseshoe Pond Drainage Basin Calculations	6.9-8
6.10-1	Turkey Pond Drainage Basin Calculations	6.10-5
6.10-2	Culverts Potentially Under Capacity for current Conditions for	6.10-4
6.11-1	West Concord Known Problems and Issues.....	6.11-2
6.11-2	West Concord Detention Ponds	6.11-3
6.11-3	West Concord Drainage Basin Calculations	6.11-6
6.11-4	Known and/or Suspected Problems in the West Concord Basin.....	6.11-5
6.12-1	Hoit Known Problems and Issues.....	6.12-2
6.12-2	Hoit Detention Ponds	6.12-3
6.12-3	Hoit Drainage Basin Calculations	6.12-6
6.12-4	Known and/or Suspected Problems in Hoit	6.12-5
Section 7	Outfall Inspections	
7-1	Outfalls Located during Dry Weather Screening.....	7-4
7-2	Results of Dry Weather Screening - In-situ and Nutrient Testing.....	7-7
7-3	Ranking of Outfalls Recommended for Further Investigations.....	7-8
Section 8	Evaluating Funding Mechanisms for a Storm Sewer Enterprise	
8-1	Estimated Annual Bills: Alternative Storm Water Funding approaches.....	8-9
Section 9	Summary of Recommendations	
9-1	Property/Traffic Impact	9-2
9-2	Pipe Size	9-2
9-3	Percent Undersized	9-3
9-4	Recurrence of the Problem	9-3
9-5	Pipe Age.....	9-4
9-6	Impact to Receiving Water	9-4
9-7	Constructability	9-5
9-8	Potential Road Projects	9-5
9-9	Prioritization Criteria Summary.....	9-6
Section 10	Capital Improvements Plan	
10-1	Stormwater Management Projects and total Scores	10-5
10-2	Stormwater Management Projects and total Scores (by area).....	10-9

Figures

Section 4	Detailed Study Area No. 1: “Terrible Trapezoid”	
4-1	Terrible Trapezoid Study Area	4-2
4-2	Main Storm Drain Lines through the Terrible Trapezoid Study Area.....	4-4
4-3	Hyetographs of Design Storms.....	4-7
4-4	Watersheds of Main Storm Drain Lines	4-8
4-5	Profile of Cross Country Main Storm Drain Line	4-13
4-6	Profile of Spruce Street Main Storm Drain Line.....	4-14
4-7	Profile of State Street Main Storm Drain Line	4-17
4-8	Recommendations for Follow-up.....	4-22
Section 5	Detailed Study Area No. 2: “Washington Street”	
5-1	Washington Street Basin Study Area.....	5-8
5-2	Datasheet for Manhole Inspections.....	5-9
5-3	Fully and Partially Inspected Manholes	5-10
5-4	Manholes with Highest Priority for Follow-up.....	5-11
5-5	Manholes having Pipes with 90-100 Percent Debris.....	5-12
5-6	Pipes and Inverts/Shelves in Fair to Poor Condition	5-13
Section 6	Remaining Sub-Basin Investigations	
6.2-1	Runoff Coefficients by Land Use.....	6.2-4
6.2-2	Velocities for upland method of estimating time of concentration.....	6.2-7
6.2-3	Sample Drainage Basin	6.2-11
6.3-1	Heights Sub-Basin	6.3-6
6.3-2	Concord Heights Drainage Basin - Connectivity Diagram.....	6.3-7
6.3-3	Concord Heights Drainage Basin - Connectivity Diagram.....	6.3-8
6.4-1	Turkey River Sub-Basin	6.3-5
6.4-2	Turkey River Drainage Basin - (TF) - Connectivity Diagram.....	6.3-6
6.5-1	Penacook Sub-Basin	6.5-7
6.5-2	Penacook Drainage Basin - (PN) - Connectivity Diagram.....	6.5-8
6.6-1	Fisherville Sub-Basin.....	6.6-6
6.6-2	Fisherville Drainage Basin - (FV) - Connectivity Diagram.....	6.6-7
6.7-1	Oak Hill Sub-Basin	6.7-7
6.7-2	Oak Hill Drainage Basin - (OH1) - Connectivity Diagram.....	6.7-8
6.7-3	Oak Hill Drainage Basin - (OH2) - Connectivity Diagram.....	6.7-9
6.8-1	Hospital Sub-Basin	6.8-6
6.8-2	Hospital Drainage Basin - (H) - Connectivity Diagram.....	6.8-7
6.9-1	Horseshoe Pond Sub-Basin	6.9-7
6.9-2	Horseshoe Pond Drainage Basin - (HP1, HP2 & HP3) - Connectivity Diagram.....	6.9-8

6.10-1	Turkey Pond Sub-Basin	6.10-6
6.10-2	Turkey Pond Drainage Basin – (TP) – Connectivity Diagram	6.10-7
6.11-1	West Concord Sub-Basin	6.11-7
6.12-1	Hoit Sub-Basin	6.12-7
6.12-2	Hoit Drainage Basin – Connectivity Diagram.....	6.12-8
Section 7	Outfall Inspections	
7-1a	Drainage System Map Showing GPS Located Outfalls.....	7-10
7-1b	Drainage System Map Showing GPS Located Outfalls.....	7-11
7-1c	Drainage System Map Showing GPS Located Outfalls.....	7-12
7-1d	Drainage System Map Showing GPS Located Outfalls.....	7-13
7-1e	Drainage System Map Showing GPS Located Outfalls.....	7-14
7-1f	Drainage System Map Showing GPS Located Outfalls.....	7-15
7-1g	Drainage System Map Showing GPS Located Outfalls.....	7-16
7-2	Field Sheet for Outfall Investigation.....	7-17
Section 9	Summary of Recommendations	
9-1	Drainage Problem Areas.....	9-10